



DIVISION OF FIRE SAFETY

155 WASHINGTON AVENUE  
ALBANY 10, N. Y.

# ANALYSIS OF SCHOOL FIRE INSPECTION REPORT

Settlement House  
Nursery School  
Three Mile Harbor Road  
East Hampton L.I.N.Y.

## DISTRIBUTION

- ☐ School Principal (2)
- ☐ Diocesan Superintendent
- ☐ Inspector
- ☐ Local Fire Department
- ☐ County Fire Coordinator
- ☐ Files (2)

### CONDITIONS FOUND TO EXIST

June 7, 1967

8. All exit doors should swing outward to permit free passage of occupants to the exterior of the building.

8c. Sufficient exit signs should be provided in order that all means of egress will be readily identified in time of emergency. These signs should be plainly legible with letters not less than 4½" high and with the strokes of each letter not less than ¾" wide.

10. Every classroom, unless it has a direct exit to the outside should be equipped with at least one window of such size and design to permit egress through such window.

11e. The fire department should be notified of the conduct of a drill and be requested to attend, on occasion.

12. Every building of student occupancy should be equipped with an adequate fire alarm system.

21. The boiler room and fuel storage areas should be separated from the remainder of the building by fire-resistant walls and ceilings. The door to the boiler room should be self-closing and equally resistant to flame and heat as the walls and/or the ceilings.

21a. Same as 21.

31. All curtains, drapes, etc., in places of assembly should be of fire retardent material or should be flame-proofed.

32. All places of assembly in excess of 2,000 square feet in area should be equipped with emergency lighting which is independent of the normal electric service.

Inspected by Mr. G. Billy Swett, Fire Chief Box 582 East Hington, NY.

PLEASE CONSULT THE INSPECTOR TO DETERMINE EXACT DEFICIENCIES.

PLEASE USE OTHER SIDE OF THIS FORM FOR YOUR COMMENTS ON THESE CONDITIONS.